



Presser foot protection wiring CN40 white wire is disconnected (as shown in the picture)

Button delivery sensor
After thread trimming, the tie rod contacts the sensor to send the button

